BK 23, Agency Index Placer **COORDINATES (Optional)** Metric U.S. Survey Foot **Epoch Date** Complies with Public Resources Code §§8890-8902 8773 Other: Rebuilt Pre-Construction OF CORNER RECORDS PACE Referenced Post-Construction

CORNER RECORD

Document Number 20210013 City of Rocklin County of Brief Legal Description Center radius point Rio Court, Mission Hills Unit No. 2, Bk. L of Maps, Pg. 44 Sec. 18 **CORNER TYPE** Government Corner X Control Elevation Meander Property Units Rancho Other Horizontal Datum Χ Zone November 5, 2020 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 T. 11 N., R. 7 E., M.D.B. & M. PLS Act Ref.: 8765(d) X 8771 Left as found Established Corner/ Monument: Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Replaced original found monument per C.R. 23/44 on 11/05/2020 with countersunk survey spike and washer stamped LS 5914 based upon the ties established per C.R. 23/44 after the original monument was destroyed as a result of construction. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on February 5, 2021 Exp.12-31-202 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed P.L.S.) or R.C.E. No. 8373

BPELSG-2016

County Surveyor's Comment

Page 1 of 2

